

1953-61 C Body Coupe/Hawk

Rubber Parts & Rubber Kit

Windshield gasket	1942X1	\$ 79.00	Door run (fuzzystrip) (4)	800507X8	\$ 38.00
Door sill seals, pair	800401X4	\$ 15.00	Fuzzystrip ret. clip (30)	1624X1	\$.50 ea
Door weatherstrip set	800400X11	\$ 36.00	Back glass gasket	2035X1	\$ 79.00
Cowl seal	298965	\$ 15.00	Gas lid bumpers (2)	261419	\$ 2.00 ea.
Vent seal set	303392-3	\$130.00 pr.	Rear vln. bmprs. (2)(53-54)	274974	\$ 2.50 ea.
Vent division seal (2)	800797	\$ 15.00 ea.	Rear vln. bmprs. (5) 1955-61	287427	\$ 2.50 ea.
Door glass channel (2)	800504	\$ 24.00 ea.	Hood bumpers (8)	274974	\$ 2.50 ea.
Channel retainer clips (2)	271475	\$ 3.00 ea.	Hood bumpers (2) 1953-55	289864	\$ 3.50 ea.
Rigid dr. glass channel (2)	800807	\$ 32.00 pr.	Hood bumpers (2) 1956-61	1312038	\$ 3.50 ea.
Quarter glass seal set	303678-9	\$130.00 pr	Air vent lid seals (2)	284991	\$ 6.00 ea.
Cushion, Q-glass to frame	304064	\$ 18.00 pr.	Loctite Weatherstrip adhesive	30540	\$ 12.00
Trunk seal (spliced corners)	1347074	\$ 65.00			

KIT PRICE: \$695. (KIT # RK95R)
TOTAL VALUE IF PURCHASED SEPARATELY: \$784.

GLASS

		Clear Glass	Green Glass	Green W/Shade	Gray (Limo) Glass w/ shade
Windshield	CH306	\$279.00	\$289	\$335	\$350
Vent glass (tempered)	CH2976	\$ 28. ea.	\$ 30. ea.		\$ 35. ea.
Door glass	CH4442	\$ 58. ea.	\$ 60. ea.		\$ 66. ea.
Rear quarter glass	CH2979	\$ 26. ea/	\$ 28. ea.		\$ 32. ea.
Back-glass	CHB308	\$375.	\$388.		\$399.

Side Glass Kit (6 pieces: 2 vents, 2 doors, 2 quarters), please specify color

	Clear	Green	Smoke/Grey
GK695	\$199.	\$212.	\$239.

Additional Parts (not in kits)

	Part #	Price
Accelerator pedal, type A, steel linkage connection	532800	\$26.00
Accelerator pedal, type B, rubber socket	535117	\$25.00
Boot, accelerator pedal	513536X1	\$ 6.00
Firewall insulator	298747	\$99.00
Headliner kit, vinyl	by description	\$225.00
Headliner kit, cloth	by description	\$245.00
Firewall grommets		
Main wiring, 1953-55	532909	\$ 8.00
Main wiring, 1956-61	1540836	\$ 8.00
Speedometer cable, 1953-58	1548474	\$ 8.00
O/D control cable, 1953-54	533855	\$ 3.00
Heater hose, where needed	1556859	\$ 3.50
Front fender to body shim	298340	\$12.00 each
Rear fender to body shim (at door pillar)	299850	\$ 6.50
Body Parts Manual, 1953-58 (reprint, 540 pgs.)	800436	\$40.00
Body Parts Manual, 1959-64 (reprint, 341 pgs.)	800437	\$35.00
Chassis Parts Manual, 1951-54 (reprint, 364 pgs.)	800430	\$35.00
Chassis Parts Manual, 1955-58 (reprint, 570 pgs.)	800431	\$45.00
Chassis Parts Manual, 1959-64 (reprint, 650 pgs.)	800432	\$46.00
Electronic Manuals on CD (Body, chassis, shop)		
1953-54	801454	\$19.95
1955-58 except 56J	801440	\$19.95
1959-64	801203	\$24.95

STUDEBAKER GLASS & RUBBER

4150 S. Streeter Ave., Idaho Falls, ID 83406 studebakerglass.com Phone 208 390-6306

Prices effective 10/10/2014